Synergistic D/B/M
Team:
Foundation to
Transformative
Restoration

BRANCH AVE PARK STREAM RESTORATION







PROJECT DESCRIPTION



Client Defined Goals

Improve	erosive forces from stormwater
Provide	higher quantity and quality habitat
Achieve	functional uplift: hydrologic, hydraulic geomorphic and physiochemical
Preserve	mature trees and forest
Provide	safe walking trail
Remove & Control	invasive plant species

i.e., Fill this cracked pot, Cinderella!

2018: EXISTING CONDITIONS

The Good

- Salvageable native ferns
- Salvageable stream and material
- Mature trees for shade, seed, root system
- Spring fed seep







2018: EXISTING CONDITIONS

The Bad



16-ft V shaped channel

The
"canyon"
and the
gully



Actively eroding gully

2018: EXISTING CONDITIONS

The Ugly





"That is the most depressing pipe in all of DC."

Josh Burch, DOEE



2019: COHESIVE DESIGN APPROACH

What does success look like for US?

- Support from the community
- Vertically stable
- Improve the extent of water on the landscape
- Provide "floodplain functions"
- Create a vegetation gradient
- No sewage



2019: COHESIVE DESIGN APPROACH

What is successfully constructable?

what's possible at this site with 6% to 25% slopes?





2020: SURGICAL CONSTRUCTION APPROACH



Regular reviews to assess viability and cost



Construction access



Use the channel as primary access to protect mature trees




Work around trees

https://dnr.maryland.gov/ccs/Documents/RSC_Training/RSC-Guidance.pdf



Laparoscopic Surgery



- Trail alignment used as access road to minimize tree removal.
- Strategic access to stream to save trees permitted for removal (5).
- Protect soils, avoid compaction

Pre-Op

- Salvage native plants
- Relocate saplings and shrubs
- Take vitals Observe site during storm events prior to mobilizing and during E&S installation





Constraints

- Tight LOD (limit incisions)
- Steep slopes 6-25" (sutures)
- Large trees to protect (organs)
- 2.5 outfalls Extremely flashy (hemopheliac)

Methodical planning, execution and adaptation WITH CREW to actively minimize disturbance at every stage.



Holistic Care

Take time to observe, prescribe and treat CAUSE

Code Blue: respond to unexpected events

"Specialists" on call: Designer and Client











December 2020 (Demobilization Week)




June 2021 First Growing Season





June 2021 First Growing Season



2020-2022: MAINTENANCE



Continuity and Vigilance







Same Contractor for B/M

- Knowledge of site-specific needs
- Preventive maintenance
- Ownership and accountability

High ROI

- Upfront investment in time and material
- Reduced repair and maintenance needs
- Greater assurance for long term success


2021








2022





RESULTS

Success looks like this!





RESULTS

Success looks like this!

- ✓ Support from the community Use of trail, voluntary trash pick up and update texts
- ✓ Vertically stable ACEC Award in 2021 for a functioning design
- ✓ Improve the extent of water on the landscape baseflow during extended dry periods
- ✓ Provide "floodplain functions" energy dissipation and groundwater recharge
- ✓ Create a vegetation gradient aquatic to upland species thriving including mature trees
- ✓ No sewage no more leaking sewer within project site
- √ Create the possibility for aquatic life!
 - Multiple species of dragonflies during and post construction visiting finished pools
 - Tadpoles / frogs in all lower and SPSC pools first Spring post construction
 - Stocked fish present over time

RESULTS





Donna An, PMP <u>donna@actaeongroup.com</u>





